

KEY:

A. — EXTANT PLSS CORNER NOTED. FOUND $3-\frac{1}{4}$ " ALUMINUM CAPPED, $\frac{3}{4}$ " REBAR STAMPED PLS 25971, 2003.

B. — FOUND PLASTIC CAPPED REBAR STAMPED PLS 2487, APPARENT ORIGINAL MONUMENT.

C. — SET ALUMINUM CAPPED, ½"REBAR STAMPED PLS 25971.

D. - FOUND PLASTIC CAPPED, 1/2" REBAR STAMPED PLS 25971.

F. — FOUND 5/8" REBAR.

G. - CHISLED A CROSS "+" IN BOULDER.

NOTICE:

- 1. For title, reference to a title insurance policy is recommended.
- 2. Wetlands are not addressed.
- 3. This document is certified as one, complete document. Any alteration, addition, change or edit of any part of this document supercedes and invalidates all previous information and certifications.
- This plat corrects an erroneous distance of 127.07 for the west boundary, to a distance of 122.07 as platted.
- 6. Applicable setbacks are determined either by the Town, HOA or County with jurisdiction over development of this property.
- 7. The original plat contains a distance along the north boundary that appears to be in error. This surveyor could find no original monumentation along the curved eastern boundary. What is shown and monumented hereon is a best fit approach to a solution.

This topographic survey shows the result of a field survey done by me or under my responsible charge based on facts known to me, and is not a warranty or guarantee, either expressed or implied.



